


Servicing Outdoor Power Equipment Dealers Since 1984
8 McFadden Road ⑩ Easton, PA 18045 ⑩ (800) 942-2326 ⑩ <https://shop.cadcodist.com/>

Stinger Information Bulletin

Stinger Informational Bulletin 2024-2

Gateway Applicator Battery cover

Summary: Improved battery cover was designed to replace the initial battery hold down.



Why: To reduce the possibility of fertilizer contamination and build up on the Gateway battery post(s), Stinger developed a custom fit battery cover (included) and hardware kit.

Recommendation: It is recommended to remove the existing battery hold down bracket and hardware. Clean the existing battery terminals. Make sure the battery cables are securely attached to the battery. Install the new battery cover using the provided hardware.

Kit Part Number: 95-4639

